

Ebola PPE Checklist for Hospital Healthcare Workers* Donning PPE, N95 Respirator Option

*This Ebola PPE checklist is based on the Centers for Disease Control and Prevention (CDC) guidance current as of October 20, 2014. For the latest PPE guidance from CDC, visit: http://www.cdc.gov/vhf/ebola/hcp/procedures-for-ppe.html

Donning PPE, PAPR Option

Required Supplies

- Designated clean area
- Trained observer
- Trained Healthcare worker
- Impermeable chair or bench
- Hospital grade disinfectant
- Alcohol Based Hand Rub (ABHR)
- Boot or Shoe Covers
- Washable shoes
- Surgical Scrubs or Disposable Clothing
- Gown or Coverall
- Single-use (disposable) nitrile examination gloves with extended cuffs
- Single-use (disposable) fluid-resistant or impermeable apron that covers the torso to the level of the mid-calf
- PAPR with full face shield, helmet or headpiece
- PAPR HOOD which extends to the shoulders and fully covers the neck and compatible with the selected PAPR

1. \square Engage Trained Observer : The donning process is conducted under the guidance and supervision of a trained observer, who confirms visually that all PPE is serviceable and has been donned successfully.
2. Remove Personal Clothing and Items: Change into surgical scrubs (or disposable garments) and dedicated washable (plastic or rubber) footwear in a suitable clean area. No personal items (e.g., jewelry, watches, cell phones, pagers, pens) should be brought into patient room.
3. Inspect PPE Prior to Donning: Visually inspect the PPE ensemble to be worn to ensure that it is in serviceable condition, that all required PPE and

October 20, 2014



Ebola PPE Checklist for Hospital Healthcare Workers* Donning PPE, N95 Respirator Option

*This Ebola PPE checklist is based on the Centers for Disease Control and Prevention (CDC) guidance current as of October 20, 2014. For the latest PPE guidance from CDC, visit: http://www.cdc.gov/vhf/ebola/hcp/procedures-for-ppe.html

supplies are available, and that the sizes selected are correct for the healthcare worker

healthcare worker.
4. Perform Hand Hygiene: Perform hand hygiene with ABHR. When using ABHR, allow hands to dry before moving to next step.
5. □Put on Inner Gloves: Put on first pair of gloves.
6. □Put on Boot <i>or</i> Shoe Covers.
7. □Assess PAPR type:
If a PAPR with a self-contained filter and blower unit that is integrated inside the helmet is used, then the belt and battery unit must be put on prior to donning the impermeable gown <i>or</i> coverall so that the belt and battery unit are contained under the gown <i>or</i> coverall.
* If a PAPR with external belt-mounted blower is used proceed to next step
8. Put on Gown <i>or</i> Coverall : Ensure gown or coverall is large enough to allow unrestricted freedom of movement. Ensure cuffs of inner gloves are tucked under the sleeve of the gown <i>or</i> coverall.
9. □PAPR accessories
If a PAPR with external helt-mounted blower is used, then the blower and

If a PAPR with external belt-mounted blower is used, then the blower and tubing must be on the outside of gown *or* coverall to ensure proper airflow.



Ebola PPE Checklist for Hospital Healthcare Workers* Donning PPE, N95 Respirator Option

*This Ebola PPE checklist is based on the Centers for Disease Control and Prevention (CDC) guidance current as of October 20, 2014. For the latest PPE guidance from CDC, visit: http://www.cdc.gov/vhf/ebola/hcp/procedures-for-ppe.html

10. Put on Outer Gloves : Put on second pair of gloves (with extended cuffs). Ensure the cuffs are pulled over the sleeves of the gown <i>or</i> coverall.
11. Put on Respirator : Put on PAPR with a full face-shield, helmet, or headpiece.
12. Put on a single-use (disposable) hood that extends to the shoulders and fully covers the neck must also be used. Be sure that the hood covers all of the hair and the ears, and that it extends past the neck to the shoulders.
13. Put on Outer Apron (if used): Put on full-body apron to provide additional protection to the front of the body against exposure to body fluids or excrement from the patient.
14. Verify : After completing the donning process, the integrity of the ensemble is verified by the trained observer. The healthcare worker should be comfortable and able to extend the arms, bend at the waist, and go through a range of motions to ensure there is sufficient range of movement while all areas of the body remain covered. A mirror in the room can be useful for the healthcare worker while donning PPE.
15. Disinfect Outer Gloves: Disinfect outer-gloved hands with ABHR. Allow to dry prior to patient contact.
16. \square Verify that there is no visible skin or hair is exposed.
17. □Proceed to patient contact.